




# Inspection Report

<b>Report No:</b> 83067	<b>Manufacturer:</b> Bounce Now	
<b>Tag No:</b> 43061	<b>Size:</b> 15.3m x 6.5m x 3.1m	
<b>Date:</b> 08 Jun 2021	<b>Type:</b> Assault Course	
	<b>Serial Number:</b> 01-17-78-00/01/02	

## Automated Test Sheet


Anchorage		Detail	Totally Enclosed Details		Detail	Additional Details	Detail
Anchor Points	Pass	Good	Exits	N/A		Anchor Type	PVC metal Triangle
Anchor Accessories	Pass	'D' Ring	Exit Markings	N/A		Number of Anchors	22
<b>Structure</b>			Independent Support	N/A		Open Side Fall-off Height	0.63M
Seam Security	Pass	good	Emergency Lighting	N/A		Inside Wall Height	1.8M
Stitching	Pass	3-5mm	Deflation of the User Area	N/A		Play Area	
Blower Tube	Pass	1.2M	<b>Slides</b>			Max User Height	Max No. Users
Walls & Towers	Pass	Upright	Height of Walls	Pass	0.75	1.0 metre	6
Step/Ramp Size	Pass		Run Out	Pass	H2 RO1.5	1.2 metre	6
Grounding	Pass	85Kg	Clamber Net	N/A		1.5 metre	6
Sharp Angles	Pass	None	Slide Sheet	Pass	Velcro	1.8 metre	6
Pressure	Pass	See Pictures	<b>Blower</b>				
Fall Off Height	Pass		Suitability	Pass		Place of Test	ABC Margate
Trough Depth	Pass		Inlet and Outlet Mesh	N/A		<b>Notes:</b> 2 Extra Ties down points have been added by the customer on the middle section. Make sure mats are used at all open points Make sure users crawl through the middle section and do not climb over it Roof sewn into the walls to increase user height Netting added to the slide section to increase user height 2021 pressures:- Front pressure 5.23"wg Middle pressure 4.54"wg End/Slide Pressure 4.41"wg	
Entrapment	Pass	None	Cable and Plug	Pass			
Stability	Pass	Good	Impeller	Pass			
Deflation/Evacuation	Pass	Good	Return Flap	Pass			
Air Loss	Pass	None	PAT Test	Pass			
Markings	Pass	See Pictures	Blower Type	Huawei			
Identification	Pass	See Pictures	Blower Size	1.5HP			
<b>Materials</b>			<b>Risk Assessment Notes:</b> Entrance Slits makes it very difficult to fall out so the step being a little short should be OK. Mats should be used at all points where there are no containing wall, ie at the junctions between the inflatable sections. Make Sure users crawl through the middle section and do not climb over the top.				
Fabric (Fire)	Pass						
Fabric Strength	Pass						
Zips	Pass	Covers					
Thread	Pass	Good					
Ropes	N/A						
Netting	Pass						
Windows	N/A						
Artwork	Pass	Hand Painted					

## Annual Test

I certify that the inflatable play equipment identified by means of the PIPA tag attached to the unit (number as above) was tested in accordance with the European Standard BS EN 14960 and

# PASSED

If you suspect that this report is not genuine or has been altered, you can check the equipment's test status by visiting [www.pipa.org.uk](http://www.pipa.org.uk) and entering the tag number shown above. Please report any irregularities using the contact details below.

 <a href="http://www.inflatablePIPAtesting.co.uk">www.inflatablePIPAtesting.co.uk</a>	<b>Report Expiry Date:</b> 07 Jun 2022
	<b>Inspection Body:</b> Inflatable PIPA Testing
	<b>Print Name:</b> David Tofton
	<b>Signature:</b> <i>DTofton</i>

See continuation sheet notes here: [pipa.org.uk/notes/83067](http://pipa.org.uk/notes/83067)